




THE CARNEY MILLING CO.
 NO WATCHMAN - POWER WATER -
 HEAT SYSTEM - LIGHTS OIL LAMPS -
 TWO "PERFECTION" CHEMICAL EXTINGUISHERS.
 SOME WATER BARRELS AND PAILS.

MACHINERY.
 BELT - SAWING
 AT FLY - 3 STAND ROLLS, 1 RUN STONE,
 1 STAND FEED ROLL, 1 FOOD ATTACHMENT MILL,
 1 CORN CRACKER, 1 HOPPER SCALES,
 3 PLATFORM SCALES, 2 FLOUR PACKERS.
 20 FLY - 4 FLOUR DRESSERS (ROLLS),
 2 PUMMERS, 1 CORN DUSTER,
 1 EXHAUST FAN, 1 CORN SHELTER,
 3 FLOUR DIES, 7 CORN DIES.
 30 FLY - 1 WOLF CYRATOR, 2 SHING SIFTERS,
 2 FLOUR DRESSERS, 1 SHORTS DUSTER,
 1 WHEAT SCOURER, 2 WHEAT SEPARATORS,
 1 CORN SCOURER, 1 WHEAT PUMMER,
 ELEVATOR HEADS,
 32 STAND OF ELEVATORS.

Scale of Feet.

3

43

7

45