

POPULATION 79,000.

Prevailing Winds WEST

1
COLUMBUS OHIO.
(2379)

WATER FACILITIES - Very Good, Holly System of Water Pipes, 3 Sets of Pumps, Capacity 18 Millions Gallons per Hour, Average daily Consumption 3 1/2 Millions Gallons per Annum. Water can be raised 750 feet. Pumping Works 57 Miles of Water Pipes, 534 Double Hydrants, Average Domestic Pressure 10 lbs., Average Fire Pressure 110 lbs. per Sq. Inch.

FIRE DEPARTMENT - 101d 39 Men, 21 Horses, 2 Steam Fire Engines in Reserve, 8 Independent Hose Carts, 3 Chemical Engines, 1 Hook & Ladder Truck, 1000 of 2 1/2" hose in good condition, 65 Fire Alarm Telegraph Boxes.

Note - The following additions are to be made to the Fire Department about June 1st:
8 Men - 2 Horses - 2 Hose Carts - 2400' 2 1/2" Hose

Columbus Ohio
February 11, 1887

Sunborn Map Co.

The undersigned have examined the new work of your Surveyor, Mr. Gardner, and consider it correct, and in all respects a very valuable addition to your map of Columbus Ohio. We believe that all existing risks of any importance have been surveyed and that your map will now furnish all information necessary to a clear understanding on the part of the Companies of Columbus insured.


Chas. Museum
MANAGER.
F. Schwan
H. Bancroft
Lauterbach & Gilber
Geo. B. Choate
John A. Red

16 W. Bliss
J. M. Shedd
Geo. S. Deane
Woodruff & Ayers
W. H. Bull
John H. Wood

Columbus, Ohio.
February 11, 1887.

Dear Sirs: After examining, thoroughly, the new and revised sheets of your Columbus Map, I find that they furnish ample information regarding the Mercantile and Manufacturing risks which have been added to the industries of Columbus within the past few years and can heartily recommend the map as revised, to all Insurance Companies doing business in Columbus.

Yours Very Truly
H. O. Kane Secretary
The Franklin Insurance Co
of Columbus, Ohio



KEY

Fire Wall	Bin	As	Roof
Frame Partition			
Opening & Iron Door			
Windows - Shutters			
Stable			
Window in 1st Story			
Window in 2nd Story			
Window in 3rd Story			
Window in 4th Story			
Windows colored yellow are frame			
Red	Brick		
Blue	Stone		
Grey	Iron		
Brown	Adobe		
Green	Special		
Marked with circle and cross lined			
Indicate relative heights			
Alternate street nos are actual			
Consolidative			
Broken line near blue wood garage			
Solid	Metal		

